
Company-wide Lean (Six) Sigma Deployment

AIM

To deploy company-wide Lean (Six) Sigma program, tailor made and specific to the organization ensuring maximum return of investment.

Gap Study

Gap Study is done by our experts before launching Lean (Six) Sigma program specific to the organization. It is to understand the gap in skill/ maturity level of the organization so that the program can be designed to deliver the maximum return of investment at optimum time.

It shall help in determining the number of cycles (waves) of Lean (Six) Sigma deployment and customizing the training specific to the organization.

Its duration may vary from 1 day - 3 days depending upon the size and maturity level of the organization.

Champions/ Sponsor training

The first step towards deploying Lean (Six) Sigma is to get the buy-in of the top management and train the functional heads to convince Lean (Six) Sigma is on the top priority for the organization and that their participation is mandatory for their growth/survival in the organization.

Its duration may vary from 2 hrs -1 day depending upon the size and maturity level of the organization.

Workshop

A workshop is organized to find the viable Lean (Six) Sigma projects and the right project leaders to be trained, execute and deliver the results. The outcome the program is unique Lean (Six) Sigma project portfolio.

Its duration may vary from 1 day - 3 days depending upon the size and maturity level of the organization.

Green Belt training

ACS's unique training module by our experts' shall build the right Lean (Six) Sigma culture in the organization that shall go on benefiting the organization year on year improving the bottom line of the organization. It is a part time role, with minimum 25% of total time of Green Belt dedicated to Lean (Six) Sigma.

The duration of the Green Belt training is of standard 5 days, Accelerated Green Belt of 3 days, and project completion of 1-3 months.

Black Belt training

The trained black belts shall be capable of taking leadership position in the organization for managing the change, taking pro-active initiatives and deliver results as per the expectation of the management. It is a full time role.

Company-wide Lean (Six) Sigma Deployment

The training takes standard Black Belt 4 weeks (1 week per month) per batch, Accelerated Black Belt 2 weeks, and Black Belt project completion takes 3-6 months.

Master Black Belt training

Master Black Belts, trained and certified by us shall have the complete expertise in rolling out the program independently seeing the big picture of the organization. It is a full time role.

It takes 1 year – 3 year to train, develop and give the full expertise of Lean (Six) Sigma. A very few number of Master Black Belts are required in an organization.

Golden Hand shake

ACS and the organization shall share knowledge and experiences, after the completion of the entire program/ waves.

'right leadership and direction ensures success and growth'

::